

**South pier crossframe – bottom struct fractured** 




South pier cross-frame bottom strut fractured



All 4 exterior channels on approach spans bent.
























### STRUCTURE INVENTORY AND APPRAISAL SHEET

ITEM 10-145-08-1 02 HIGHWAY DISTRICT **GRAND FORKS** CAVALIER MAINLINE ON 03\_ COUNTY GINV. ROUTE FEATURES INTERSECTED OB STRUCTURE NO. 09 LOCATION CNTY HIWAY PEMBINA RIVER 145-08-1 5 EAST OF VANG BYPASS DETOUR LENGTH OWNERSHIP FUNCTIONAL 4 MILES 22 26 COUNTY AGENCY LOCAL 27 YEAR BUILT 28 LANES ON STRUCTURE BUILT 1919; NO RECONST 29 30 ADT 20 1987 YEAR OF ADT DESIGN LOAD APPROACH ROADWAY WIDTH 31 UNKNOWN 32 12 FEET O DEG 34 SKEW 34 SKEW
36 TRAFFIC SAFETY FEATURES
41 STRUCTURE OPEN, CLOSED OR POSTED
42 TYPE OF SERVICE
43 MAIN STRUC. TYPE
45 NO. SPANS IN MAIN UNIT
46 NO. APPROACH SPANS
47 TOTAL HORIZ. CLEARANCE
48 LENGTH OF MAX SPAN
49 STRUCTURE LENGTH
50 SIDEWALK WIDTHS
51 BRIDGE RDWY. WIDTH - CURB TO CURB
52 DECK WIDTH 0111 POSTED HIGHWAY OVER WATERWAY STEEL THRU TRUSS 15.8 FEET 100 FEET 130 FEET NONE NONE 15.8 FEET 17.8 FEET 14.06" NOT APPLICABLE 51 52 DECK WIDTH MIN. VERT. CLEARANCE OVER BRIDGE ROWY
MIN. VERT. CLEARANCE UNDER BRIDGE ROWY
MIN. LATERAL UNDERCLEARANCE-RT
MIN. LATERAL UNDERCLEARANCE-LT
WEARING SURFACE 53 54 55 NOT APPLICABLE 99.9 FEET
WOOD PLANKING
MARGINAL COND.-MAJOR REHABILITATION
OR COND.-PEDATE BEGINS OF THE PROPERTY OF THE PROP 56 58 DECK 3 POOR COND.-REPAIR REQUIRED IMMEDIATELY
4 MARGINAL COND.-MAJOR REHABILITATION
7 GENERALLY GOOD COND.-MINOR MAINTENANCE 59 SUPERSTRUCTURE 60 SUBSTRUCTURE 6 CHAN. & CHAN. PROT EST. REMAINING LIFE 10 YEARS OPER. RATING APP.RDWY.ALIGNMENT INV. RATING H - 0765 3 POOR COND.-REPAIR REQUIRED IMMEDIATELY 1 IMMED. REPAIR TO PUT BACK IN SERV.
2 INTOLERABLE--HI REPLCMNT PRIORITY
2 INTOLERABLE--HI REPLCMNT PRIORITY
7 COND. BETTER THAN PRES. MIN. STAND.
3 INTOLERABLE--HI PRIORITY OF REPAIR
05/89 66 STRUCTURAL CONDITION
DECK GEOMETRY
SAFE LOAD CAPACITY
WATERWAY ADEQUACY
APP. RDWY. ALIGNMENT
DATE OF LAST INSPECTION 67 68 70 71 90 DELAYED INSPECTION -105 CULVERT 91 92 DESCRIPTION COUNTY-OFF STRUCTURALLY DEFICIENT STRUCTURE TYPE 89

INSPECTORS NAME

SUFFICIENCY RATING

STATUS

WILSON & FLOM

24.4

#### 96 ADDITIONAL REMARKS

NO CURB. NO BRIDGE END MARKERS. RUSTY STRINGERS. VEHICLE DAMAGE TO BOTH RAILS, BOTH APPROACH SPANS. 3 TRUSS BOLTING SEVERLY RUSTED. SOUTHWEST ABUTMENT WING BADLY CRACKED AND LEANING INWARD. OUTSIDE STRINGERS BOTH APPROACH SPANS LEANING OUT DUE TO RAIL DAMAGE. ROTTED DECK PLANKS.\* POOR VERTICAL AND HORIZONTAL ROADWAY ALIGNMENT. POSTED NARROW BRIDGE-WEIGHT LIMIT 5 TONS. BUMP AT SOUTH END OF STRUCTURE

# CONT. STRINGERS

STRINGER: 1/2 = 16.7 SPACING = 24" I-BEAM 6\* 12.25 5 = 7.3 in3 3" TIMBER DECK

### RATE 4 PT

# DEAD LOAD

**ONPAD** 

BEAH! DECK: 3/12(24/2)(50) = 25MISC =  $\frac{2.75}{40 \text{ ms}}$ 

= 12.25  $0F = \frac{24}{2}/4 = 0.5$ 

DLM = .07 (40) (16.7) = 78/ FT-LBS

LIVE LOAD I = 30% ANLERS COEF = 0.1980

(HU: .198(112,000)(16.7)(1.3)(.5) = 25,791 FT-LBS

= 25,791 FT-LBS

### CARACITY

INU: 16,000 (7.3) /12 = 9,733 FT-LBS

OPR: 22,500 (7.3)/12 = 13,688 FT-185

# RATIMA

INU: 9,733 - 781 (15) = HS 5.2 25,791

OPR: 13,688 - 79! (15) = 45 7.5 25.791

### PATE 10 PT

DF = 0.5

DL COEF (DHUER) = 0.125

LLM COEF (") = 0.1912

DLH = 0.125 (40) (16.7) = 1,394 FT-LBS

LIVE LORD 1 = 30%

INU: 0.1912 (12,000) (1.3) (16.7) (.5) = 24,906 FT-LBS

Ope : = Z4,906 FT-LBS

CARACITY

0000

INU = 9,733 FT-LOS

OPR. = 13,688 FT-LBS

RATING

INU: 9733-1394 (15) = HS 5.0

*24,906* (209)

OPR: 13,688-1394 (15) = HS 7.4

24,906 (213)

ITEM 70: 36-13/36 (100) = 63.9% CODE O

POST R12-4-13

Owbach


# FLOOR BEAM


BEAM: L= 16.5' I GEAN 15 \* 39 5 = 53.8 m3

### DEAD LOAD

BEAM: = 39 #/=7FROM STRINGERS: 40(16.7)(10)/16.5 = 405 #/=7DLM:  $450(16.5)^2/8 = 15,314 = 17-185$ MISC: 450 #/=7

LIVE LOAD





LLM = 75,600 (1.3) = 98,280 FT-LBS

### CAPACITY

INU: 16,000 (53.8) /12 = 71,733 FT-LBS

OPR: 22,500 (53.8)/12 = 100,875 FT-LB5

# RATING


 $1NU: \frac{71,733-15,314}{98,280} (15) = H5 8.6$ 


OPR: 100, 875-15,314 (15) = H5 13.1 98, 280





STEEL OR TIMBER TRUSS BRIDGE REPORT State Highway Department, Bridge SFN 2807 (Rev. 8-89)

INSPECTOR W-150N & Flor DATE 6-19-50 BRIDGE NO. 10-145-08.1
THROUGH TRUSS $\nearrow$ PONY TRUSS $\square$ LENGTH = 130' BACK TO BACK OF ABUTMENTS NO. OF SPANS $\longrightarrow$ 13.6 + 13.6
NOTE: THE STANDARD PANEL NUMBERING FOR TRUSS BRIDGES IS CONSECUTIVE AND NUMBERICAL BEGINNING WITH A ZERO AT THE TRUSS—DAY, UPPER CHORD PANEL POINTS ARE NUMBERED WITH THE LETTER U, AND LOWER CHORD POINTS WITH L
CLEAR BETWEEN RAILS    1 2     3 FT.     3 FT.     12 BFT.
out to out 18:4
DRAW SECTIONS OF TRUSS MEMBERS WITH DIMENSIONS AS SHOWN AT A-A, B-B, C-C & D-D ON REVERSE SIDE.  DRAW JOINT CONNECTIONS ON REVERSE SIDE.  Shorts
TYPES OF BEAMS - FLOOR/STRINGER
TW E TW
TYPE OF FLOOR: CONCRETE TIMBER (UNDERLINE ONE)  TYPE OF CURB: CONCRETE TIMBER (UNDERLINE ONE)  TYPE OF RAIL 3 - Aucle Tron @ 12" Aport  FLOOR BEAMS: NUMBER  SPACING 167 LENGTH 19.6  SPACING 24" LENGTH 15.4 33.4 33.4 33.4 33.4 33.4 33.4 33.4 3
INTERIOR TYPE T-Bean DEPTH 6" WDTH 3/4" TW 11 12 12 12 12 STRINGERS CONTINUOUS OVER NO. 1 FLOORBEAMS DESCRIBE TYPE OF ABUTMENTS: CONCONTRACTOR OF THE STRINGERS CONTINUOUS OVER NO. 1 FLOORBEAMS
DESCRIBE TYPE OF APPROACH SPANS: Steel Striger
COMMENTS OM ITEMS AFFECTING STRENGTH:









### **BRIDGE INSPECTION REPORT**

	DISTRICT OR COUNTY	CAVALIER_ AUG 13 176
INSPECTOR LS 27AM	DATE _	AUG 13 /76
BRIDGE DECK PROFILE  Taken from N to S W to E		
Abut 1 Span 1  N W side 5./6 5./5  S E side 5./6 5./5  Paint spot o (Other) 63	Pier 2 Span 2 Pier 3  5.16 4.85 4.82  5.15 4.84 4.81  n top of NW Galssow  CEVS TO DEEK	Span 3 Abut 4  4.80 4.80  4.80 4.80
		<b>—</b> .J
STREAM PROFILE (Downstream side)		
Taken N to S W to E	on N W SE side of bridge.	
Taken on top of the curb rail at at	floor other	
Taken at atat	spaces. Water Elev.	14.3'
6.3'-9.4'-15.7'-110.	9-17.0-17.9-15.0-	10.0'-7.7
COMMENTS:		

Co. Bridge No. 145-8.1 A-A Double-Double High Iron 4,-4, 5 12-12 5 13-13; 14-14; 15-15 5:2e 2/2x 2/2x 1/4 Convected by plate 1/87 XV4 spaced 36" & 10 % B-B Double Charrel Beam 60-4; 05-6 Apple Size 6 x2 x 14 Flanges 14 12 Connected by a plate 12" X/4
YUNNING complete length Oovble Channel Beam Same as B-B D-D Double - Double Horagle Iron Size 2/2x 2/2x/4 Connected by plates 13x5x14
spaced 29" & to \$\mathbf{x}. Double - Double Mugle Took 12-01 5 4-03 5. ce 2/2 x 2/2 x X/4 Connected by Plates 7x4x44
2preed 36" \$ to 8. Double - Double Angle Iron 5. ze 3" x2/2 x 1/4 Connected by plates
7x1/x/4 greed
5paced 36" 210 2 (over) Top Lateral Strut

Deside - Double Horghe Ivory

Size 2x2x 316

Lacing 1843 316

Top Lateral

Iron Bar

Size 34

Portal


Double Horghe Iron

Size 284x 882 x44

Lucing A. & Convected by Lacing

Hughe Iron 2x2x 316

39" long



Bridge	No.	145-8.1
--------	-----	---------

Bridge I	Profile
----------	---------

Taken	from	y to s	W to E  Span 1 Pier 2 Span 2 Pier 3 Span 3 Abut h									
		Abut. 1	Span 1	Pier 2	Span 2	Pier 3	Span 3	Abut L .				
N Ø	side	5.30	5.25	523	4.93	192	492	1.91				
5 (E)	side	5.28	5.26	5.19	4.95	1.95	1.93	1.95				
n u	Paint	Strot on t	nerete 11	14 110	Cuel	Ælev.	19	5				

### Stream Profile

Taken N to S W	to E on	N W S E si	ide of bridge.	
Taken on top of the	curb	rail	floor	
Taken at Hals Piers,	Flor Bemat	spaces.	Water Elev.	14.4'
(4) 6.3	(2) 7.9	(3) 163'	(4) 192	
(5) 17.0'	(6) 18.31	(2) 13.8	(8.) 11.2	6)8.8

### NORTH DAKOTA STATE HIGHWAY DEPARTMENT

#### Secondary Roads Division

### **COUNTY BRIDGE SITE EVALUATION**

Bridge i	No. 115-8,1	
Dirage i	140.	

1	ROADWAY GEOMETRICS:  1. Degree of Curve in each d  2. Tangent Length from Brid	:	111	400	5	Al 200
,	Degree of Curve in each of the control of the	irection	1/5/			61
	<ol> <li>Degree of Curve in each d</li> <li>Tangent Length from Brid</li> <li>Roadway width and Side</li> </ol>	oge		1011	5/200	
•	4. Surface type	Slopes			2/29:3	
•	4. Surrace type	A & C 1				
(	CONTROL DEVICES:			•		
	1. CURVE Sign	[] Yes [¶No				
		In Place	Size	Condition	Color	Location from Bridge
	2. SINGLE LANE	[ ] Yes [L]-No	<u> </u>			
•	Signing	In Place	Size	Condition	Color	Location from Bridge
	3. NARROW BRIDGE	[] Yes [9 No]				
	Sign	In Place	Size	Condition	Color	Location from Bridge
	4. LOW CLEARANCE	[] Yes [] No				
		In Place	Size	Condition	Color	Location of Sign
	5. WEIGHT LIMIT					
	5. WEIGHT LIWIT	[] Yes [] No	Size	Condition	Color	Location of Sign
				Condition		
	6. Advance Warning for Weight limit	[] Yes [c] No			0-1	Location of Sign
	The state of the s	In Place	Size	Condition	Color	Location of Sign
	7. Speed Limit	[] Yes [J No				
		MPH.	Size	Condition	Color	Location of Signs
	8. Bridge End Markers	[] Yes [] No	<del></del>			
		In Place	Size	Condition	Color	Location of Markers
	9. Shoulder Delineation	Yes XNo				
		In Place	Size	& Condition	Color	Location
1	10. Centerline					
•	TO. Centerline	[ ] Yes ['] No		State Condition	on (Poor) (Good)	(Excellent)
				State Condition	on (Foor) (Good)	(Excellent)
1	11. Edge Line	[] Yes [] No	<del></del>			
		In Place		State Condition	on (Poor) (Good)	(Excellent)
1	12. Guard Rail	[] Yes [] No				
	(Type)	In Place		State Type (C	Cable) (Steel Rail)	(Other)
	ACCESS ON APPROACH:	Comments regardi	na siaht dis	tanes and provinci	tf	inta
	AGGEGG ON ALL NOAGH.	Comments regarding Fair	ng agnituis			
_	ACCIDENT EXPERIENCE:	(To be completed	in Central (	Office of North Da	kota State High	hway Department)
					·	

# TRUSS BRIDGE REPORT

	CO. BRIDGE NO. 1415-8.1
COUNTY CAUGITEY LOCATION North Olga Township FEATURE CROSSED PEMBINA ROVER YEAR BUILT	BRIDGE NO
FEATURE CROSSED PENDING ROVER YEAR BUILT	DATE INSPECTED 23 Ava 72
THROUGH TRUSS PONY TRUSS L= 1301511  DIRECTION OF INVENTORY N S E W (UNDERLINE ONE)	BACK TO BACK OF ABUTMENTS NO. OF SPANS Three
UI 2 100 8 SPAN LENGTH	VERT. AND HORIZ. CLEARANCES
NO. OF PANELS	STANCE.
FLOOR BEAMS 996 H.W.	CLEAR BET 19 9 13 1 13 1 CLEAR 15 10 11
	STRINGERS
SIONS AS SHOWN REVERSE SIDE.	OF TRUSS MEMBERS WITH DIMEN- AT A-A, B-B, C-C & D-D ON
TYPES  THICK- NESS  WIDTH  WIDTH	THICK- NESS WIDTH WIDTH WIDTH
Lo I- BEAM W	F BEAM CHANNEL BEAM
TYPE OF FLOOR: PCC TIMBER (UNDERLINE ONE) THICK TYPE OF CURB: PCC TIMBER ( " ") SIZE:	NESS 3" high x 13" wide
TYPE OF RAIL SIZE SIZE	2x2x3/16
FLOOR BEAMS: NUMBER SPACING SPACING	18" Flanges 7/16 1/16
TYPE	
STRINGERS: NUMBER SPACING 24	
EXTERIOR: TYPE Chan well Beat DEPTH 6 WIDTH_	THICKNESS 3/6
INTERIOR: TYPE T- BOWN DEPTH 6 WIDTH	THICKNESS
DESCRIBE TYPE OF ABUTMENTS Con energy - Good	Condition
DESCRIBE TYPE OF PIERS COSSION - Bood	Candition
DESCRIBE TYPE OF APPROACH SPANS I-Beyon - Sain	1e 05 truss
HEAD DIAMETER OR SIZE OF RIVETS 1/8 head Win.	SIDE)



10-145-08.1 Broken Planks on Bridge Deck

10-145-08.1

Structure Number:

# North Dakota Department of Transportation

## **Bridge Inventory - Structure Inventory And Appraisal Sheet**

Structure Number: 10-145-	08.1		
200 System Designation	3 – County Off	Classification	
201 Status	Structurally Deficient	12 Base Highway Network	Not on Base Network
202 Sufficiency Rating	30.80	20 Toll	3 On free road
Identification		21 Maint Responsibility	02 County Hwy Agency
02 Highway District	Devils Lake District	22 Owner	02 County Hwy Agency
03 County	Cavalier	26 Functional	Rural, Local
04 City	FREMONT TOWNSHIP	37 Historical Significance	2 Br eligible for NRHP
05 Inventory Route	Route On Structure	100 Defense Highway Designation	0 Not a STRAHNET hwy
4 County Hwy 1 Mainline	00000 0 N/A (NBI)	101 Parallel Structure Designation	No    bridge exists
06 Feats Intersect	PEMBINA RIVER	102 Direction of Traffic	3 1-lane Br for 2-way
09 Location	5 EAST OF VANG	103 Temporary Structure Designation	Not Applicable (P)
11 Milepoint	0.000	104 Highway System of Inventory Rte	0 Not on NHS
13 LRS Inv Route. Subroute	-1 -1 48d 54' 02.00"	105 Federal Lands Highways	Not applicable
16 Latitude	98d 01' 06.00"	110 Designated National Network	0 Not part of natl netwo
17 Longitude	571954.1 5416850.7	112 NBIS Bridge Length	
		226 Functional Under Condition	
	wn (P) -2.00 %		6 Satisfactory
99 Border Bridge Struct No.  Structure Type and Material	-	58 Deck	4 Poor
• •	Steel	59 Superstructure	5 Fair
43 Main Struct Type Truss - Thru	Steel	60 Substructure	7 Minor Damage
	3 Steel	61 Chan. & Chan. Protection	N N/A (NBI)
44 Approach Struct Type	3 3(66)	62 Culvert and Retaining Walls  Load Rating and Posting	N WA (NDI)
45 No. Chang in Main Unit	1	•	
45 No. Spans in Main Unit 46 No. Approach Spans	2	31 Design Load	Unknown
107 Deck Struct Type	8 Wood or Timber	41 Structure Open, Closed or Posted	B Posting Recommended
108 Wearing Surface	7 Wood or Timber	63 Operating Rating Method	2 AS Allowable Stress
Membrane	0 None	64 Oper. Rating HS 7	12 Tons
Dk Protect	None	65 Inventory Rating Method	2 AS Allowable Stress
208 Dk Overburden 1	None	66 Inv. Rating HS 4	9 Tons
Age and Service	110110		0 >39.9% below
<del>-</del>	r Reconstructed -1	70 Bridge Posting 209 Posted in "Tons"	00 Tons
		Appraisal	00 10118
42 Type of Service	1 Highway - On 5 Waterway - Under	67 Structural Condition	2 Intolerable - Replace
28 Lanes on Structure	2	68 Deck Geometry	2 Intolerable - Replace
	0 Year of ADT 2014	69 Underclear. Vert & Horiz	N Not applicable (NBI)
109 Average Daily Truck Tra		71 Waterway Adequacy	7 Above Minimum
19 Bypass, Detour Length	20 Miles	72 App. Rdwy. Alignment	3 Intolerable - Correct
Geometric Data	· Williou	36 Traffic Safety Features	0 0 0 0
10 Min Vert Clearance	14 Ft. 5 In.	113 Scour Critical	U Unknown Scour
32 Approach Roadway Width		Inspections	
33 Bridge Median	0 No median	90 Date of Last Inspection	September 16, 2014
34 Skew	0.00	91 Designated Inspection Frequency	24 Months
35 Structure Flared	0 No flare	92 Critical Feature Inspected / 93 Critical	Feature Last Inpsection Dt
47 Total Horizontal Clearance	e 17.4 Feet	Fracture Critical Y	24 07/30/2012
48 Length of Max Span	99 Feet	Underwater N	
49 Structure Length	129.92 Feet	Other Special N	
50 Curb/Sidewalk Widths	0.0 Ft Rt-Side	218 Channel Profile Y	48 10/08/2014
	0.0 Ft Lt-Side	207 Transporter Erector Routes and Sites	-1
51 Bridge Rdwy Width - Curb		212 Structure Load Rated	01/01/1901
or Bridge Harry Wilder Care	17.7 Feet	213 Federal Aid Project Number	
52 Deck Width	18.4 Feet	214 Delayed Inspection	Not Applicable
53 Min Vert Clear. Over Bridge		216 Inspector	Horn, Ebensteine
54 Min Vert Underclearance	0 Ft. 0 In.	Navigation Data	
	N Feature not hwy or RR	38 Navigation Control	Permit Not Required
55 Min Lateral UnderClear	Rt 327.8 Feet	39 Navigation Vertical Clearance	0 Feet
	N Feature not hwy or RR	40 Navigation Horizontal Clearance	0 Feet
56 Min Lateral UnderClear	Lt 0.0 Feet	111 Pier or Abutment Protection	Unknown (NBI)
210 Culvert / 211 Description	l	116 Minimum Navigation Vertical Clearan	ce -1 Feet

January 09, 2015

# North Dakota Department of Transportation Bridge Inventory - Structure Inventory And Appraisal Sheet

**SEC 409** 

Structure Number: 10-145-08.1

Elm/Env	Description	Units	Total Qtv	% in 1	1-Qtv St	% in 2	2-Qtv St	% in 3	3-Qtv St	% in 4	4-Qtv St	% in 5	5-Qtv St
31 / 1	Timber Deck	(SF)	2,390	0%	0	100%	2,390	0%	0	0%	0	0 %	0
107 / 2	Paint Stl Opn Girder	(LF)	1,289	0%	0	0%	0	20%	258	80%	1,031	0 %	0
121 / 2	P/Stl Thru Truss/Bot	(LF)	197	0%	0	0%	0	0%	0	100%	197	0%	0
126 / 2	P/Stl Thru Truss/Top	(LF)	197	0%	0	0%	0	0%	0	100%	197	0%	0
152 / 2	Paint Stl Floor Beam	(LF)	98	0%	0	0%	0	0%	0	100%	98	0%	0
202 / 2	Paint Stl Column	(EA)	4	0%	0	0%	0	100%	4	0%	0	0%	0
215 / 2	R/Conc Abutment	(LF)	36	0%	0	100%	36	0%	0	0%	0	0%	0
231 / 2	Paint Stl Cap	(LF)	36	0%	0	0%	0	0%	0	100%	36	0%	0
330 / 1	Metal Rail Uncoated	(LF)	259	0%	0	0%	0	95%	245	5%	14	0%	0
401 / 2	Wings	(EA)	4	75%	3	0%	0	25%	1	0%	0	0%	0

Remarks: Date 11/17/2004 - New planks for 300 ft. at various locations.

NBI Remarks: No curb or bridge end markers.Rusty girders. Vehicle damage to railings both sides. Poor horizontal roadway alignment.Posted narrow bridge. Some new deck planks added. Transverse brace between columns on pier 3 is broke. Oct.12,2007 no visible cracks on fracture critical members. One bolt missing & one bolt loose on u3 west side northwest approach rail missing. 140 ft. of broken planks at various locations.

9/16/14 - 300 ft of new bridge planks at various locations.

**Alert Code 2:** Southwest abutment wing badly cracked and leaning inward. Outside stringers both approach spans leaning out due to rail damage.

# STRUCTURE INVENTORY AND APPRAISAL SHEET

```
ITEM
                                                                                                                                                                           25-106-40-0
  02 HIGHWAY DISTRICT
                                                                                                                                                                                          MINOT
  03 COUNTY
                                                                                                                                                                                     MCHENRY
  05 INV. ROUTE
0 EATURES INTERSECTED
1 TRUCTURE NO.
                                                                                                                                         SOURIS RIVER
                                                                                                                                                                 MAINLINE ON
                                                                                                              CNTY HIWAY
                                                                                                                                                                                   106-40.0
  09
        LOCATION
                                                                                                                                         BRIDGE TO PARK IN VELVA
  19 BYPASS DETOUR LENGTH
22 OWNERSHIP
26 FUNCTIONAL
                                                                                                                                                                                     3 MILES
                                                                                                                                                                      COUNTY AGENCY
                                                                                                                                                                                          LOCAL
  27 YEAR BUILT
28 LANES ON STRUCTURE
                                                                                                                BUILT 1921; RECONST 1968
        ADT
YEAR OF ADT
DESIGN LOAD
                                                                                                                                                                                                  85
                                                                                                                                                                                            1987
  31
                                                                                                                                                                                     UNKNOWN
         APPROACH ROADWAY WIDTH
                                                                                                                                                                                     36 FEET
0 DEG
 34 SKEW
36 TRAFFIC SAFETY FEATURES
41 STRUCTURE OPEN, CLOSED OR POSTED
42 TYPE OF SERVICE
43 MAIN STRUC. TYPE
45 NO. SPANS IN MAIN UNIT
46 NO. APPROACH SPANS
47 TOTAL HORIZ. CLEARANCE
48 LENGTH OF MAX SPAN
49 STRUCTURE LENGTH
50 SIDEWALK WIDTHS
51 BRIDGE RDWY. WIDTH - CURB TO CURB
52 DECK WIDTH
53 MIN. VERT. CLEARANCE OVER BRIDGE RDWY
54 MIN. VERT. CLEARANCE UNDER BRIDGE RDWY
55 MIN. LATERAL UNDERCLEARANCE—RT
56 MIN. LATERAL UNDERCLEARANCE—LT
57 WEARING SURFACE
         SKEW
                                                                                                                                                                                            0000
                                                                                                                                                                                       POSTED
                                                                                                                                                  HIGHWAY OVER WATERWAY
STEEL THRU TRUSS
                                                                                                                                                                                20.0 FEET
99 FEET
102 FEET
                                                                                                                                                       NONE
                                                                                                                                                                                            NONE
                                                                                                                                                                                18.7 FEET
                                                                                                                                                                                20.0 FEET
                                                                                                                                                                   NOT APPLICABLE
                                                                                                                       NOT APPLICABLE
NOT APPLICABLE
NOT APPLICABLE
WOOD PLANKING
8 GOOD COND. - NO REPAIRS NEEDED
 58 DECK
59 SUPERSTRUCTURE
60 SUBSTRUCTURE
61 CHAN. & CHAN. PROT
61 CHAN. & CHAN. PROT
65 APP.RDWY.ALIGNMENT
66 INV. RATING
67 STRUCTURAL CONDITION
68 DECK GEOMETRY
70 SAFE LOAD CAPACITY
71 WATERWAY ADEQUACY
72 APP. RDWY. ALIGNMENT
90 DATE OF LAST INSPECTION
LO5 DELAYED INSPECTION
  58
         DECK
                                                                                                       GENERALLY GOOD COND.-MINDR MAINTENANCE
GENERALLY GOOD COND.-MINDR MAINTENANCE
                                                                                                         GENERALLY GOOD COND.-MINOR MAINTENANCE
29 YEARS
                                                                                                                                                                                            H - 18
                                                                                                    7 GENERALLY GOOD COND.-MINOR MAINTENANCE
                                                                                                             4 MEETING MIN. ADEQUACY
3 INTOLERABLE—HI PRIORITY OF REPAIR
5 BETTER THAN MIN. ADEQUACY
6 COND. EQUAL TO PRES. MIN. STAND.
6 COND. EQUAL TO PRES. MIN. STAND.
01/89
         DELAYED INSPECTION -
CULVERT
DESCRIPTION
  91
  89
         STRUCTURE TYPE
                                                                                                                                                                             COUNTY-OFF
  95 STATUS
94 SUFFICIENCY RATING
                                                                                                                                                  FUNCTIONALLY OBSOLETE
                                                                                                                                                                                            63.7
```

INSPECTORS NAME

STAMBAUGH & HENRICHS

96 ADDITIONAL REMARKS

NO END MARKERS. LAMINATED TIMBER DECK OVERLAYED WITH 2" OF ASPHALT. STEEL FLOOR BEAMS AND STRINGERS 40% RUSTED. 1 PART OF LOWER CHORD AND TRUSS END COVERED WITH DIRT AT THE S.E. CORNER.\* FOOTING FOR EAST ABUTMENT EXPOSED. PLANKS FOR SIDEWALK SHOW MODERATE DECAY. EAST BANK OF RIVER SEVERELY ERODED.

### WIDTH 718' : RATE ZLANE

# STRINGERS (CONT)

42=16.67' SDACING = 30" I BEAM 10+25.4 5= 24.41M3
3"TIMBER DECK 1" ASPHALT

# RATE 4 PT

### DEAD LOAD

2002

22-141 22-142 22-144

OMP DAD

BEAM: = 24.4

DECK:  $\frac{3}{12}(\frac{3}{12})(50) = 31$ .

ASPHALT.  $\frac{3}{12}(\frac{3}{12})(150) = 31$ HISC  $\frac{3}{12}(\frac{3}{12})(150) = \frac{3}{12}$ 

DF, NU = 39/2/3.75 = 0.6667 DFORD = 39/2/4 = 0.625 DL COEZ (ANGEL) = .07

DLM = .07(90)(16.67) = 1751 FT-185

LIVELOAD I = 30% Angers = . 1977

INU: , 1977 (12,000) (16.67) (1.3) (.6667) = 34, 277 FT-LBS

OAR: .1977 (12,000) (16.67) (1.3) (.625) = 32, 133 FT.LBS

# CAPACITY

INU: 16,000 (24.4) /12 = 32,533 FT.CBS

OPE: 22,500 (24.4)/12 = 45,750 =7. LBS

### RATING

 $1 \text{MU}: \frac{32,533 - 1751}{34,277} (15) = \text{HS } 13.5$ 

OPE: 45.750-1751 (15) = H5 20.5 32,133 (237)

# RATE 10 PT.

DFINT 0.6667 DFORE = 0.625 DL coep (AMCD) = 0.125 LLMcoep (") = 0.1911

DEM = ./25 (90) (16.67) = 3, 126 FT. LBS

LIVE LOAD I = 30%

INU: .1911 (12,000)(1.3) (16.67) (.6667) = 33,132 FT.LBS

OPR: 1911 (12,000) (1.3) (16.67) (.625) = 31,060 FT. LBS

CAPACITY

200

22-141 22-142 22-148

AMPAG.

NU = 32,533 FT.LBS

OPR = 45,750 FT.LRS

RATING

|NU: 32,533-3.126 (15) = H5 13.333,132 (224)

OPR: 45,750-3.126 (15) - HS 20.6
31,060


# FLOORBEAM

L= 20' I.BEAM 24 \* 85 5= 180 m3


# DEAD LOAD

$$\frac{10}{770} = \frac{10}{770}$$

LIVE LOAN



LLMORE = 109-39=7P = 109, 200 FT. LBS



# CAPACITY

### RATING

22-141 50 SMEETS 22-142 100 SMEETS 22-144 200 SWEETS








#### STEEL OR TIMBER TRUSS BRIDGE REPORT


State Highway Department, Bridge SFN 2807 (Rev. 8-89)

INSPECTOR Stambaugh - Henrichs DATE 11/29/90 BRIDGE NO. 25-106-20.0 THROUGH TRUSS D PONY TRUSS D LENGTH = BACK TO BACK OF ABUTMENTS NO. OF SPANS . NOTE: THE STANDARD PANEL NUMBERING FOR VERT. AND HORIZ. CLEARANCES TRUSS BRIDGES IS CONSECUTIVE AND NUMBERICAL BEGINNING WITH A ZERO AT THE TRUSS—BID. UPPER CHORD PANEL POINTS ARE NUMBERED WITH THE LETTER U, AND LOWER CHORD POINTS WITH L. NO. OF PANELS 5. <u>/\_</u>FT. LO CLEAR. BETWEEN RAILS FLOOR BEAMS 20./ FT. 15.0 FT. /2.3 FT. CLEAR ROADWAY Deck 0.7.0-26.3' Sidewalk on Lt. - 6.Z FLOORBEAMS TRUSS DRAW SECTIONS OF TRUSS MEMBERS WITH DIMENSIONS AS SHOWN AT A-A, B-B, C-C & D-D ON REVERSE SIDE. DRAW JOINT CONNECTIONS ON REVERSE SIDE. TYPES OF BEAMS - FLOOR/STRINGER LO **WDTH** WIDTH MOTH I-BEAM WF BEAM **CHANNEL BEAM** TYPE OF FLOOR: CONCRETE TIMBER (UNDERLINE ONE) THICKNESS TYPE OF CURB: CONCRETE TIMBER (UNDERLINE ONE) SIZE TYPE OF RAIL Angle From FLOOR BEAMS: NUMBER SPACING TYPE I-Beam DEPTH - 6875 16. FLOOR BEAMS: NUMBER LENGTH SPACING TYPE Channel **EXTERIOR:** . WIDTH DEPTH . TYPE T-Beam DEPTH S OVER NO. LILLY 3, LI 10 - WIDTH STRINGERS CONTINUOUS OVER NO. L.L. ... FLOORBEAMS DESCRIBE TYPE OF ABUTMENTS: tor west abutmen None DESCRIBE TYPE OF PIERS: DESCRIBE TYPE OF APPROACH SPANS: COMMENTS ON ITEMS AFFECTING STRENGTH: abutments. Appr- 23









## TRUSS BRIDGE REPORT

<u>.                                    </u>	CO. BRIDGE NO.
COUNTY ME HEARY LOCATION VELVA PARK	BRIDGE NO. 106 - 40
FEATURE CROSSED Sours River YEAR BUILT	DATE INSPECTED 12-6-72
THROUGH TRUSS PONY TRUSS L = 102'  DIRECTION OF INVENTORY N S E W (UNDERLINE ONE)	BACK TO BACK OF ABUTMENTS NO. OF SPANS /
NO. OF PANELS 4  FLOOR BEAMS  SPAN LENGTH  H.W.	VERT. AND HORIZ. CLEARANCES
SIONS AS SHOWN REVERSE SIDE.	STRINGERS  OF TRUSS MEMBERS WITH DIMEN- AT A-A, B-B, C-C & D-D ON  BCu m 3 OF BEAMS  THICK- NESS  WIDTH  WIDTH  WIDTH  ZZ  THICK- VESS
Lo I- BEAM	F BEAM CHANNEL BEAM
٠, ٠	2"x2"
TYPE SPACING SPACING SPACING WIDTH	4 7/9 THICKNESS 1/8
STRINGERS: NUMBER 9 SPACING STRINGERS: TYPE Channel DEPTH 10 WIDTH INTERIOR: TYPE Frame DEPTH 10 WIDTH	2/2 THICKNESS 3/8"  THICKNESS 3/8"
DESCRIBE TYPE OF ABUTMENTS CONCrate (cost end) Tra	CATOR LIMBER (MEST)
DESCRIBE TYPE OF PIERS Clane	
DESCRIBE TYPE OF APPROACH SPANS TONE	
HEAD DIAMETER OR SIZE OF RIVETS On truss 11/4"	

#### NORTH DAKOTA STATE HIGHWAY DEPARTMENT


### Secondary Roads Division

#### COUNTY BRIDGE SITE EVALUATION


Bridge No.	106-40

PURPOSE: To gather pertinent data concerning the approach roadways at bridge sites on local roads.


Α.	RO	ADWAY GEOMETRICS:	0 1		la t	1 L 1 T G	<b>.</b>
	1.	Degree of Curve in each d	irection <u>Dridy</u>	'i 15 5	Reved a	taat 15°	From street & cur
	2.	Tangent Length from Brid	ige <u>is al</u>	sout 5	so long		
	3.	Roadway width and Side	Slopes <i>.36</i>	o stre	et -	No dita	hes city street
	4.	Surface type	Pavement				
3.	СО	NTROL DEVICES:	Pavement Bridge &	park c	losed in	the win	ter
	1.	CURVE Sign	[] Yes [X No				
			In Place	Size	Condition	Color	Location from Bridge
	2.	SINGLE LANE	[] Yes [X] No				
		Signing	In Place	Size	Condition	Color	Location from Bridge
	3	NARROW BRIDGE	[ ] Yes [X] No				
	Ů.	Sign	In Place	Size	Condition	Color	Location from Bridge
	4.	LOW CLEARANCE	[] Yes [★ No	<del> </del>		<del></del>	
			In Place	Size	Condition	Color	Location of Sign
	E	MICICUTALINALT		·		1	
	5. WEIGHT LIMIT	[ ] Yes 🔀 No	Size	0	Color	Location of Sign	
			10113	0,20	Condition	1 20101	Location of orgin
	6. Advance Warning		[] Yes [XTNo				
		for Weight limit	In Place	Size	Condition	Color	Location of Sign
	. Slo ω 7. S <del>peed Limit</del>		Yes No	24"x 24"	000d_	Back ou Vellow	80' from bridge
			MPH.	Size	Condition	Color	Location of Signs
	g	Bridge End Markers	I I Van IVI Na			<u> </u>	
	0.	Bridge Erid Markers	[ ] Yes [X] No	Size	Condition	Color	Location of Markers
					Gondinon		
	9.	Shoulder Delineation	[] Yes [X No				
			In Place	Size	& Condition	Color	Location
	10.	Centerline	[] Yes [X No				
			In Place		State Cond	ition (Poor) (Goo	d) (Excellent)
	11.	Edge Line	[] Yes [XT No				
			In Place		State Cond	ition (Poor) (Goo	d) (Excellent)
	10	C D.:1		ı			
	12.	Guard Rail (Type)	[ ] Yes [X No In Place		C+ T	(0.11.) (01.5	W 10.4 - X
			In Flace	l	State Type	(Cable) (Steel Ra	II) (Other)
C.	AC	CCESS ON APPROACH:	Comments regards $\mathcal{B}_{c}$ $\neq$ $\mathcal{L}$	ing sight dist	•		oints.
		COLDENT EVER PLENCE					
D.	AC	CCIDENT EXPERIENCE:	(10 be completed	in Central C	ITTICE OF North [	Jakota State Hi	gnway Department)




Elevation



106-40





end plank		2عر	J Flank	•	
dank. Spikerti ok to cleate		//	Laminated Floor		4"x 18" x2"-3"  Specing Block
18 0 x 10 - Boits 80					
x 32:-0"		-	Pearing Plate Re	1300)	
ng Pionk	**************************************		16 255-187.6		ATULE A POLOGO
7°x 92-0	7-7		4"x/2"x 32"-0"		the man with the second
ling Plank			4 x/2 x 32-0		
*x 4'- 0"		1		4"x5"x 4-0"	1 1 12
sing Stack		. د		Spacing Brock	

A	BUTI	ME!	NT #	4	QL	IAN	TITI	ES	FC	R T	WO	ABUTMENTS	;	ABUTI	1EN	T #2	
TREATED TIME	BER-FU	iLL	SAWN	ROUGH					ΗA	ROWAR	Ε (	GALVAN-ZED)	TREATED T	IMBER-	FULL.	SAWN	ROUGH
DESCRIPTION	1.90. 3	SIZE	LENGTH	5 0.1	กสร	RIFT	OY	, NO.	15 Z E	LENGTH	1 :	MOLTEC	DESCRIPTION	, NC.	SIZE	LENGTH	F. B. M.
PILE ANCHOR	1	47.12	32 -0"	1,78	5 P	- BC	_7 S	12	,	٠٠٠٠ .	CAP	TO PILE ABUT, 1 B 2	- LE ANCHER	i	2 x 12	28.0"	1/2
BACKING PLANK	4	3.8	32'-00	256	TIV	SER BE	2LT5	4	/"	z-0	RET	19 PLATE TO	PACKING PLAT	vr , Z	3x/2	32'-0'	192
BACKING PLANK	10	3 x 2	32"-0"	920				4	17	1-10"	BE A	HINSPLATE TO	PILE CLEATS	12	نَ دُوُ	4.0"	120
WING PLANK	16	32.2	· .'4'-0"	672				:	T	1	i		PILE CAP	1	6124	28'-0"	896
."	12	3x./2	121.00	.72	្តីការខ	ER BO	LTS	5	: :2*	2'-2"	ABU	CLEAT TO PILING	SPACING BLOC			2'-0"	70
	2	1.2	10-0-	60			•	:30	58	3.00	CLE	ATS TO PILE ANCHOR	\$760 Y. B. P.	AFF /	7.0	16'-0"	4.7
	7 ,	2	3	- / -	4			-		/							

















BRIDGE NUMBER 25-106-40.0  DATE OF PHOTO 4-13-87  DIRECTION Fast Appr
COMMENTS
07



BRIDGE NUMBER 25-106-40.0  DATE OF PHOTO 4-13-87  DIRECTION Morth Elev.
COMMENTS
07 0. 4 4



BRIDGE NUMBER 25-106-40.0  DATE OF PHOTO 1/4/89  DIRECTION  COMMENTS Manufacturers plate  Thus bridge





Structure Number:

## North Dakota Department of Transportation

### **Bridge Inventory - Structure Inventory And Appraisal Sheet** 25-106-40.0

200 System Designation	3 – County Off	Classification		
201 Status Functi	onally Obsolete	12 Base Highway Network		Not on Base Network
202 Sufficiency Rating	63.40	20 Toll		3 On free road
Identification		21 Maint Responsibility		02 County Hwy Agency
02 Highway District	Minot District	22 Owner		02 County Hwy Agency
03 County	McHenry	26 Functional		Rural, Local
04 City	VELVA CITY	37 Historical Significance		2 Br eligible for NRHP
	te On Structure	100 Defense Highway Designation		0 Not a STRAHNET hwy
5 City Street 1 Mainline 00000	0 N/A (NBI)	101 Parallel Structure Designation		No    bridge exists
oo i oato iiitoiooot	MOUSE RIVER	102 Direction of Traffic		2 2-way traffic
09 Location	IN VELVA	103 Temporary Structure Designation		Not Applicable (P)
11 Milepoint	0.000 -1 -1	104 Highway System of Inventory Rte		0 Not on NHS Not applicable
13 LRS Inv Route. Subroute	48d 03' 35.00"	105 Federal Lands Highways		0 Not part of natl netwo
16 Latitude	100d 56' 10.00"	110 Designated National Network 112 NBIS Bridge Length		o Not part of flati fletwo
17 Longitude GPS Coordinates XY 355739.7	5324744.9	226 Functional Under		
		Condition		
98 Border Bridge Unknown (P)	-2.00 /6	58 Deck		7 Good
99 Border Bridge Struct No.  Structure Type and Material	_	** = ****		6 Satisfactory
43 Main Struct Type	Steel	59 Superstructure 60 Substructure		6 Satisfactory
Truss - Thru	Otoci	61 Chan. & Chan. Protection		7 Minor Damage
	Unknown (NBI)	62 Culvert and Retaining Walls		N N/A (NBI)
44 Approach Struct Type	, ,	Load Rating and Posting		
45 No. Spans in Main Unit	1	31 Design Load		
46 No. Approach Spans	0	31 Design Load		Unknown
* * * * * * * * * * * * * * * * * * * *	Vood or Timber	41 Structure Open, Closed or Posted		P Posted for load
108 Wearing Surface	6 Bituminous	63 Operating Rating Method		2 AS Allowable Stress
Membrane	0 None	64 Oper. Rating HS 20		36 Tons
Dk Protect	None	65 Inventory Rating Method		2 AS Allowable Stress
208 Dk Overburden 301	Asphalt	66 Inv. Rating HS 13		24 Tons
Age and Service		70 Bridge Posting		5 At/Above Legal Loads
27 Yr Built 1921 106 Yr Reconstruc	cted 1968	209 Posted in "Tons"		04 Tons
	lighway - On	Appraisal		0. 10113
, po o. oo	erway - Under	67 Structural Condition		6 Equal Min Criteria
28 Lanes on Structure	2	68 Deck Geometry		2 Intolerable - Replace
29 ADT 85 30 Year of Al	OT 2014	69 Underclear. Vert & Horiz		N Not applicable (NBI)
109 Average Daily Truck Traffic	-1.00	71 Waterway Adequacy		6 Equal Minimum
19 Bypass, Detour Length	124 Miles	72 App. Rdwy. Alignment		6 Equal Min Criteria
Geometric Data		36 Traffic Safety Features		0 0 0 0
10 Min Vert Clearance	14 Ft. 12 In.	113 Scour Critical		U Unknown Scour
32 Approach Roadway Width	23 Feet	Inspections		
33 Bridge Median	0 No median	90 Date of Last Inspection		April 11, 2014
34 Skew	0.00	91 Designated Inspection Frequency		24 Months
35 Structure Flared	0 No flare	92 Critical Feature Inspected / 93 Critical	Feature L	ast Inpsection Dt
47 Total Horizontal Clearance	18.7 Feet	Fracture Critical Y	24	02/05/2013
48 Length of Max Span	91 Feet	Underwater N		
49 Structure Length	102.03 Feet	Other Special N		
50 Curb/Sidewalk Widths 0.	0 Ft Rt-Side	218 Channel Profile Y	48	08/07/2012
6.	2 Ft Lt-Side	207 Transporter Erector Routes and Sites	3	-1
51 Bridge Rdwy Width - Curb to Curb		212 Structure Load Rated		01/01/1901
	19.0 Feet	213 Federal Aid Project Number		
52 Deck Width	26.2 Feet	214 Delayed Inspection		Not Applicable
53 Min Vert Clear. Over Bridge	12 Ft. 3 In.	216 Inspector		Olson, Beavers, Medler
54 Min Vert Underclearance	0 Ft. 0 In.	Navigation Data		
N Feature	not hwy or RR	38 Navigation Control		Permit Not Required
55 Min Lateral UnderClear Rt	327.8 Feet	39 Navigation Vertical Clearance		0 Feet
	not hwy or RR	40 Navigation Horizontal Clearance		0 Feet
56 Min Lateral UnderClear Lt	0.0 Feet	111 Pier or Abutment Protection		Unknown (NBI)
210 Culvert / 211 Description		116 Minimum Navigation Vertical Clearar	nce	-1 Feet

# North Dakota Department of Transportation Bridge Inventory - Structure Inventory And Appraisal Sheet

**SEC 409** 

Structure Number: 25-106-40.0

Elm/Env	Description	Units	Total Qtv	% in 1	1-Qtv St	% in 2	2-Qtv St	% in 3	3-Qtv St	% in 4	4-Qtv St	% in 5	5-Qtv St
32 / 1	Timber Deck/AC Ovly	(SF)	1,927	100%	1,927	0%	0	0%	0	0%	0	0 %	0
113 / 1	Paint Stl Stringer	(LF)	715	0%	0	0%	0	0%	0	100%	715	0 %	0
121 / 1	P/Stl Thru Truss/Bot	(LF)	203	0%	0	0%	0	0%	0	100%	203	0 %	0
126 / 1	P/Stl Thru Truss/Top	(LF)	203	0%	0	0%	0	100%	203	0%	0	0 %	0
152 / 1	Paint Stl Floor Beam	(LF)	112	0%	0	0%	0	0%	0	100%	112	0 %	0
206 / 1	Timber Column	(EA)	6	0%	0	100%	6	0%	0	0%	0	0 %	0
215 / 1	R/Conc Abutment	(LF)	26	0%	0	100%	26	0%	0	0%	0	0 %	0
216 / 1	Timber Abutment	(LF)	26	0%	0	100%	26	0%	0	0%	0	0 %	0
235 / 1	Timber Cap	(LF)	26	0%	0	100%	26	0%	0	0%	0	0 %	0
330 / 1	Metal Rail Uncoated	(LF)	203	0%	0	0%	0	100%	203	0%	0	0 %	0
332 / 1	Timb Bridge Railing	(LF)	203	0%	0	100%	203	0%	0	0%	0	0 %	0
401 / 1	Wings	(EA)	4	100%	4	0%	0	0%	0	0%	0	0%	0

Remarks: Paint system failure.

NBI Remarks: Angle iron bridge rails have minor to moderate damage. Top lateral strut between end posts, at west end, bent downward 2". Roller bearings, under west end of truss, are fixed by rust. Outside chord from L0 to L1 Rt, is bent upward 1.5". Nut, for lateral brace, is cracked on left end of second floor beam (west side). Turnbuckle on counter between U3 and L2 prime left, is cracked. A few lateral braces, between floor beams are bent. Some diagonals are loose. East abutment has several hairline and well defined random cracks. Footing is partially exposed. Lower chords, along north side, heavily rusted.

Alert Code 1: Retainer plate, over the top of lateral brace and its connecting pin, is severely delaminated by rust (NW corner of truss). Eye, at end of lower lateral brace that attaches to SW truss end post, has lost half its section from corrosion. West abutment cap twisting and rotating back bearing only on the back of piling leaving a 1" gap between cap and piling on west end. Cap also has a 3' horizontal crack. East bearing is buried in the dirt.