

Site 2: Structure No 17-042.967



Photo 1: Spall repair in north curb (1 SF)



Photo 2: Spall repair in south curb (1 SF)





Photo 3: Spall repair at Abutment 1 (7 SF)



Photo 4: Spall repair at Abutment 1 (7 SF)



Site 2: Structure No 17-042.967



Photo 5: Spall repair at Abutment 4 (15 SF)



Photo 6: Spall repair at Abutment 4 (12 SF/ Girder Bay = 60 SF)





Photo 7: Spall repair at Abutment 4 (11 SF)