




#3

Span3 west side spall with
exposed rebar rusting



#4

NE wing spalled