

February 20, 2009

For more information:

Bob Walton, District Engineer, (701) 239-8900
Communications, 701-328-4444

Motorists cautioned to watch for bump in road on I-29 near the Mayville exit

The North Dakota Department of Transportation urges motorists to use caution and reduce their speed when traveling on southbound Interstate 29 near the Mayville exit. A bump has developed due to frost underneath the roadway surface. The area is signed and marked. The bump and signing is expected to be present until warmer temperatures thaw the subgrade.