

Site 3: Structure No 19-118.258



Photo 1: Spall repair at Abutment 1 (5 SF)



Photo 2: Spall repair at Abutment 1 (16 SF)



Site 3: Structure No 19-118.258



Photo 3: Spall repair at Abutment 1 (11 SF)



Photo 4: Spall repair at Abutment 3 (18 SF)



Site 3: Structure No 19-118.258



Photo 5: Spall repair at Abutment 3 (5 SF/Girder Bay = 35 SF)



Photo 6: Spall repair at Abutment 3 (5 SF)