

Site 4: Structure No 52-222.340



Photo 1: Spall repair at north barrier in Span 1 (2 SF)



Photo 2: Spall repair at north barrier in Span 2 (3 SF)

Site 4: Structure No 52-222.340



Photo 3: Spall repair at north barrier in Span 2 (3 SF)



Photo 4: Spall repair at north barrier in Span 3 (2 SF)



Site 4: Structure No 52-222.340



Photo 5: Spall repair at south barrier in Span 3 (4 SF)



Photo 6: Spall repair at south barrier in Span 3 (3 SF)

Site 4: Structure No 52-222.340



Photo 7: Spall repair at south barrier in Span 1 (2 SF)



Photo 8: Spall repair at southwest wingwall (6 SF)



Site 4: Structure No 52-222.340



Photo 9: Spall repair at northwest wingwall (6 SF)



Photo 10: Spall repair at northeast wingwall (6 SF)

### Site 4: Structure No 52-222.340



Photo 11: Spall repair at southeast wingwall (6 SF)